



SLIP TEST

DATE: 29/07/2020

ADDRESS: 228 La Trobe street, Melbourne VIC 3000

CLIENT: Stanmore/Sadif

TEST METHOD: Wet Pendulum Testing, AS 4586-2013

SLIDER PREPARATION: Abrasice Paper P400, Pink lapping paper wet

18 085 322 390
 3 SPRAY AVENUE
 Mordialloc VIC 3195
 Australia
 1300 88 44 18

CONDUCTED BY: LACHLAN COUACAUD

SURFACE: GREY TUNDRA

RUBER SLIDER USED: SLIDER 96

TEST METHOD: WESSEX PENDULUM SKID TESTER

WEATHER: 17° c

SPECIMEN NUMBER	Location	CONDITION	DIRECTION OF TESTS	MEAN BPN LAST THREE SWINGS
1	Level 61 Spa Room	As Found	Anticipated Direction of Pedestrian Traffic	56
2	Level 61 Spa Room	As Found	Anticipated Direction of Pedestrian Traffic	56
3	Level 61 Spa Room	As Found	Anticipated Direction of Pedestrian Traffic	57
4	Level 61 Spa Room	As Found	Anticipated Direction of Pedestrian Traffic	56
5	Level 61 Spa Room	As Found	Anticipated Direction of Pedestrian Traffic	56
Mean BPN SRV				
Classification		P5	Result	56